
Meter Engineering and Automation Metering Standards Bulletin

Issued By:	Number:	Date Issued:
Meter Engineering	2015-002	04/23/2015

OPENWAY METERS FAILURE UNDER INVESTIGATION

Purpose of Communication

Meter Engineering has identified a handful of OpenWay Centron Form 2S 240V meters that have failed due to overvoltage. As you can see in the picture below the front of the polycarbonate meter cover has been blown off. The investigation is ongoing and your assistance is required.



ACTION Required by All Field Personel:

Please contact Florin Moldovan of Meter Engineering at (313) 389-7617 to report such sites and assist with the field investigation.

Written By /s/ Florin Moldovan Principal Engineer Meter Engineering