PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner			FIRE REPORT - STRUCTURE		
		INCIDENT NUMBER: DMI 2012 06 15 23 01			
Location of Incident:	BURDOCK MISSION BC				
# of Occupants (At time of fire): 2	# of Injured: 0 #	of Deaths: 0	Total D	Dollar Loss Estimate: \$ s.22	
Related to Wildland Interface Fire: NO	Property Value: s.22	Content V	Value: \$ s.22	Total Value at Risk: \$ s.22	
Code Nan	ne : Code Description	n			
PROPERTY COMPLE	X : 3400 RESIDENTIAL	- SINGLE DETA	ACHED		
PROPERTY CLASSIFICATIO	N : 3110 YEAR-ROUND	USE DWELLIN	G - 1-FAMILY		
GENERAL CONSTRUCTION	N : 2000 PROTECTED C	OMBUSTIBLE	CONSTRUCTIO	ON - WOOD PROTECTED BY PLAS	
BUILDING HEIGH	T : 0020 2 STORIES AB	OVE GRADE			
GROUND FLOOR ARE	A : 2000 101 TO 500M2	(1077 - 5382FT2)		
YEAR OF CONSTRUCTION	N : 0000 CANNOT BE D	ETERMINED			
MANUAL FIRE PROTECTIO	N : 7000 NO MANUAL I	FIRE PROTECT	ION		
OUTSIDE FIRE PROTECTIO	N: 1000 PUBLIC HYDR	ANT PROTECT	TON & FIRE DE	PARTMENT	
SPRINKLER PROTECTIO	N : 7000 NO SPRINKLE	R PROTECTION	1		
AUTOMATIC FIRE ALARM SYST	E : 1000 NO FIRE ALAF	RM SYSTEM			
SMOKE ALARM OPERATIO	N: 1000 ALARM ACTIV	ATED - ASSIS	TED OCCUPAN	T(S) IN EVACUATING	
INITIAL DETECTIO	N: 7000 VISUAL SIGHT	TING OR OTHE	R MEANS OF P	ERSONAL DETECTION (E.G. S	
TRANSMISSION OF ALARM	M : 1000 911				
FIRE SERVIC	E : 3000 COMPOSITE -	CAREER & VO	LUNTEER/PAID	O-ON-CALL FIRE DEPARTMENT	
INCIDEN	T : 1000 FIRE - FIRE DE	PARTMENT A	ITENDED		
ACTION TAKE	N : 3000 EXTINGUISHE	D BY FIRE DEF	PARTMENT		
METHOD OF FIRE CONTROL	L : 4300 38MM/42MM (l 1/2"/1 3/4") HC	OSE - 2 OR MOR	E HAND LINES	
FIRE ORIGIN, LEVE	L : 3000 GROUND FLO	OR, GRADE LE	VEL OR GRADI	E TO 3M (10FT)	
FIRE ORIGIN, ARE	A : 7600 EXTERIOR WA	LL			
EXTENT OF FIR	E: 6000 EXTENDED BE	EYOND PROPER	RTY OF ORIGIN	1	
EXTENT OF DAMAG	E: 6000 EXTENDED BE	EYOND BUILDI	NG OF ORIGIN		
IGNITING OBJEC	T : 5900 ELECTRICAL I	DISTRIBUTION	EQUIPMENT -	UNCLASSIFIED (DESCRIBE)	
FUEL OR ENERG	Y : 6000 ELECTRICITY				
FORM OF HEA	Т: 6000 НОТ ОВЈЕСТ -	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE			
MATERIAL FIRST IGNITE	MATERIAL FIRST IGNITED: 3000 EXTERIOR WALL COVERING, SURFACE, FINISH - INCLUDES EAVE				

MATERIAL FIRST IGNITED : 3000 EXTERIOR WALL COVERING, SURFACE, FINISH - INCLUDES EAVE ACT OR OMISSION : 4100 PART FAILURE, LEAK, BREAK

Investigating OfficerLAFC Badge #TelephoneReportDateSCHMIDT, MIKE539604-820-37942012-06-21

Remarks:

A PART FAILURE OF THE ELECTRICAL METER BASE LOWER LEFT LUG. THE METER ITSELF WAS ELEIMINATED AS A CAUSE OF THIS FIRE.

Investigating Officer SCHMIDT, MIKE LAFC Badge # 539
 Telephone
 ReportDate

 604-820-3794
 2012-06-21

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DMI 2012 06 15 23 01

PROVINCE OF BRITISH Ministry of Justice Emergency Management H	COLUMBIA BC / Office of the Fire Commissioner	FIRE REPORT - STRUCTURE (NAMES) INCIDENT NUMBER: DMI 2012 06 15 23 01		
Name no. Name Address	: 1 : s.22 : BRITISH COLUMBIA	Name Status : OWNER Phone : s.22		
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: 1. PAYNE, GLENN : 1. PAYNE, TRAVIS & ASSOCIATES : 1. s.22 : 1. BCAA : 1. s.22			
LOSS ESTIMATES: Property Loss : \$ s.22 REMARKS:	Content Loss : s.22	Total Loss : \$ s.22		

MAJOR LOSS, ROOF COMPROMISED, CARPORT DESTROYED

Investigating Officer SCHMIDT, MIKE

LAFC Badge # 539

Telephone ReportDate 604-820-3794 2012-06-21

Incident Report