

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CPG 2013 09 20 09 01

Location of Incident: **1705 MILL RD
 PRINCE GEORGE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: \$ **s.22**

Related to Wildland Interface Fire: **NO** Property Value: \$ **s.22** Content Value: \$ **s.22** Total Value at Risk: **s.22**

Code Name :	Code Description
PROPERTY COMPLEX :	3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION :	3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION :	0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	0000 CANNOT BE DETERMINED
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	0000 CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE :	0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA :	0000 CANNOT BE DETERMINED
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	LAFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2014-02-23

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CPG 2013 09 20 09 01**

Remarks:

FULLY INVOLVED 3 STOREY HOUSE WITH HEAVY SMOKE AND FLAMES SHOWING FROM THE 2ND FLOOR/ROOF OF CHARLIE/DELTA. CREWS FOUND THE ENTIRE CHARLIE SIDE (ALL 3 FLOORS) INVOLVED IN FIRE WITH THE SIDING ALREADY BURNED OFF A LARGE PORTION OF THE HOUSE. CONFIRMED THIS WAS A DEFENSIVE OPERATION AND ORDERED 2 1/2' LINE TO BE USED ALPHA SIDE TRYING TO SLOW FIRE SPREAD TO ALPHA. APPROXIMATELY 10 MINUTES IN, THE OVERHEAD GARAGE DOOR OPENED SPONTANEOUSLY AND 2 DOGS RAN OUT OF THE GARAGE. NEIGHBOR PROVIDED A WRITTEN STATEMENT STATING THAT HE HEARD A TREE FALL AT APPROXIMATELY 0830 HOURS AND WHEN HE NOTICED IT FELL ON HIS NEIGHBORS POWER LINE HE CALLED BC HYDRO AT APPROXIMATELY 0835 HOURS. HE LEFT THE NEIGHBORHOOD FOR WORK AT APPROXIMATELY 0845 HOURS AND DID NOT SEE ANY SMOKE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2014-02-23

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CPG 2013 09 20 09 01**

Name no. : 1
 Name : s.22
 Address : 0

Name Status : OWNER
 Phone : s.22

Claims Adjuster Name :
 Claims Adjuster Firm :
 Claim Number :
 Insurance Company :
 Policy Number :

LOSS ESTIMATES:

Property Loss : \$ s.22 Content Loss : \$ s.22 Total Loss : \$ s.22

REMARKS:

Name no. : 2
 Name : s.22
 Address : 0

Name Status : OWNER
 Phone : s.22

Claims Adjuster Name :
 Claims Adjuster Firm :
 Claim Number :
 Insurance Company :
 Policy Number :

LOSS ESTIMATES:

Property Loss : \$s.22 Content Loss : \$s.22 Total Loss : \$s.22

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2014-02-23

