Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CPA 2013 07 31 16 02

Location of Incident: 4683 MARGARET STREET
PORT ALBERNI BC V9Y6H1

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$0

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

Code Name: Code Description

PROPERTY COMPLEX: 5600 COMMERCIAL CENTRE INCLUDING FUEL DISPENSING (MAY INCLUDE RES

PROPERTY CLASSIFICATION: 5930 BUILDER'S SUPPLY SALES

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 0051 1951 TO 1960

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 6000 SHUT OFF GAS, OIL, ELECTRICITY

METHOD OF FIRE CONTROL: 9500 REMOVAL/SHUT OFF FUEL

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 7600 EXTERIOR WALL

EXTENT OF FIRE: 1000 CONFINED TO OBJECT OF ORIGIN

EXTENT OF DAMAGE: 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN

 $IGNITING\ OBJECT\ :\ 5900\ ELECTRICAL\ DISTRIBUTION\ EQUIPMENT\ -\ UNCLASSIFIED\ (DESCRIBE)$ 

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT :  $2000\,$  SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 9500 INSULATION, ELECTRIC - CONFINED TO ELECTRICAL EQUIPMENT - IN

ACT OR OMISSION: 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer LAFC Badge # Telephone ReportDate
THOEN, RANDY 1957 250-720-2542 2014-04-14

http://www.ofc.gov.bc.ca/OFC/IncidentReport.jsp?incidentId=251289

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CPA 2013 07 31 16 02

## Remarks:

PORT ALBERNI FIRE DEPARTMENT RESPONDED TO A REPORT OF HYDRO TRANSFORMER FAILURE IN THE AREA OF 4683 MARGARET STREET ON JULY 31, 2013. UPON ARRIVAL, FIRE CREWS FOUND THAT THE ISSUE WAS CAUSED BY A HYDRO METER CHANGE OUT BEING COMPLETED BY A CORIX CONTRACTOR. WHILE REMOVING THE OLD METER, A FAILURE OCCURRED THAT CAUSED AN ARC FAULT WHICH ENERGIZED THE METER BASE AND MAST. IN ADDITION TO THE CONDUCTORS INSIDE THE MAST, THE PHONE AND CABLE LINES APPEARED TO HEAT UP AND SMOKE. BC HYDRO ATTENDED THE SCENE TO REMOVE SERVICE TO THE BUILDING AND MAKE THE SCENE SAFE, FIRE CREWS INVESTIGATED THE INTERIOR AND EXTERIOR OF THE BUILDING TO CHECK FOR FIRE EXTENSION AND FOUND NONE. REPAIRS TO THE ELECTRICAL SERVICE ARE REQUIRED TO BE COMPLETED BY A QUALIFIED 3RD PARTY PRIOR TO RE-ENERGIZING THE BUILDING.

Investigating Officer THOEN, RANDY LAFC Badge #

1957

Telephone 250-720-2542

ReportDate 2014-04-14

Page 3 of 4 **Incident Report** 

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CPA 2013 07 31 16 02

Name no. : 1

Name :

Address

s.22

Name Status Phone

: WITNESS

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: \$0

Content Loss: \$0

Total Loss: \$0

REMARKS:

**Investigating Officer** THOEN, RANDY

LAFC Badge #

1957

Telephone 250-720-2542

ReportDate 2014-04-14 Incident Report Page 4 of 4