

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**

INCIDENT NUMBER: **CSY 2014 07 30 03 01**

Location of Incident: **15321 111 AVE
 SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **3** # of Deaths: **0** Total Dollar Loss Estimate: **\$600,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$800,000** Content Value: **\$200,000** Total Value at Risk: **\$1,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION :	3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION :	2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	1000 1 TO 100M2 (1 - 1076FT2)
YEAR OF CONSTRUCTION :	2001 2001
MANUAL FIRE PROTECTION :	7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION :	1000 SMOKE ALARM DEVICE
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	4700 VEHICLE STORAGE - INCLUDES GARAGE, CARPORT. (EXCLUDES OUTSID
EXTENT OF FIRE :	6000 EXTENDED BEYOND PROPERTY OF ORIGIN
EXTENT OF DAMAGE :	6000 EXTENDED BEYOND BUILDING OF ORIGIN
IGNITING OBJECT :	5400 PANEL BOARD, SWITCHBOARD - INCLUDES FUSE, CIRCUIT BREAKER
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	1200 INTERIOR WALL COVERING, SURFACE MATERIAL - PLASTIC
ACT OR OMISSION :	4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
SHEEL, DANIEL	1810	604-543-6700	2014-08-12

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE**
 INCIDENT NUMBER: **CSY 2014 07 30 03 04**

Location of Incident: **15321 111 AVE
 SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$5,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$5,000** Total Value at Risk: **\$5,000**

Code Name :	Code Description
PROPERTY CLASSIFICATION :	8610 AUTOMOBILE - INCLUDES CARS, LIGHT TRUCKS AND VANS, SINGLE BO
MANUAL FIRE PROTECTION :	7000 NO MANUAL FIRE PROTECTION
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, AREA :	8500 VEHICLE - PASSENGER AREA
EXTENT OF FIRE :	6000 EXTENDED BEYOND PROPERTY OF ORIGIN
IGNITING OBJECT :	8900 EXPOSURE - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	8000 EXPOSURE FIRE
FORM OF HEAT :	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED :	9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION :	4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	LAFC Badge #	Telephone	ReportDate
SHEEL, DANIEL	1810	604-543-6700	2014-08-12

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE**
 INCIDENT NUMBER: **CSY 2014 07 30 03 05**

Location of Incident: **15321 111 AVE
 SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$6,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$6,000** Total Value at Risk: **\$6,000**

Code Name :	Code Description
PROPERTY CLASSIFICATION :	8610 AUTOMOBILE - INCLUDES CARS, LIGHT TRUCKS AND VANS, SINGLE BO
MANUAL FIRE PROTECTION :	7000 NO MANUAL FIRE PROTECTION
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, AREA :	8500 VEHICLE - PASSENGER AREA
EXTENT OF FIRE :	6000 EXTENDED BEYOND PROPERTY OF ORIGIN
IGNITING OBJECT :	8900 EXPOSURE - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	8000 EXPOSURE FIRE
FORM OF HEAT :	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED :	9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION :	4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
SHEEL, DANIEL	1810	604-543-6700	2014-08-12

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**
 INCIDENT NUMBER: **CSY 2014 07 30 03 06**

Location of Incident: **15317 111 AVE
 SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$400,000** Content Value: **\$100,000** Total Value at Risk: **\$500,000**

Code Name :	Code Description
PROPERTY COMPLEX :	3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION :	3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION :	2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	2000 2000
MANUAL FIRE PROTECTION :	7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	7900 STRUCTURAL AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	6000 EXTENDED BEYOND PROPERTY OF ORIGIN
EXTENT OF DAMAGE :	6000 EXTENDED BEYOND BUILDING OF ORIGIN
IGNITING OBJECT :	8900 EXPOSURE - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	8000 EXPOSURE FIRE
FORM OF HEAT :	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED :	9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION :	5900 CONSTRUCTION, DESIGN OR INSTALLATION DEFICIENCY - UNCLASSIFI

Investigating Officer	L AFC Badge #	Telephone	ReportDate
SHEEL, DANIEL	1810	604-543-6700	2014-08-12

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**

INCIDENT NUMBER: **CSY 2014 07 30 03 07**

Location of Incident: **15321 111 AVE
 SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$400,000** Content Value: **\$100,000** Total Value at Risk: **\$500,000**

Code Name :	Code Description
PROPERTY COMPLEX :	3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION :	3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION :	2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	2000 2000
MANUAL FIRE PROTECTION :	7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	7900 STRUCTURAL AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	6000 EXTENDED BEYOND PROPERTY OF ORIGIN
EXTENT OF DAMAGE :	6000 EXTENDED BEYOND BUILDING OF ORIGIN
IGNITING OBJECT :	8900 EXPOSURE - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	8000 EXPOSURE FIRE
FORM OF HEAT :	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED :	9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION :	5900 CONSTRUCTION, DESIGN OR INSTALLATION DEFICIENCY - UNCLASSIFI

Investigating Officer	LAFC Badge #	Telephone	ReportDate
SHEEL, DANIEL	1810	604-543-6700	2014-08-12

